

Date and Time reported to the City	Estimated Date and Time Excursion began	Estimated Date and Time Excursion ended	Method used to estimate date and time Excursion began	Operator arrival Date and Time	Address	Street	Cross Street	Zip Code	Longitude	Latitude	Asset Number	Destination(s) (e.g. combined sewer system, separate storm drain, surface water, ground, residence, business)	Fully capatured and routed to Comined Sewer System (Yes/No)
Jun 21, 2016 6:05:34 PM	See Information Worksheet Row 2	Jun 22, 2016 2:48 PM	See Information Worksheet Row 4	Jun 22, 2016 7:08:30 AM	548	ORTEGA ST	11TH AVE	94122	122.46894	37.75479	P-124122	See Information Worksheet Row 13	See Information Worksheet Row 14
Jun 24, 2016 11:27:44 AM	See Information Worksheet Row 2	Jun 24, 2016 4:55 PM	See Information Worksheet Row 4	Jun 24, 2016 2:46:25 PM	265	HESTER AVE	PENINSULA AVE	94134	122.39945	37.71311	N-18496	See Information Worksheet Row 13	See Information Worksheet Row 14

All or a portion entered a conveyance that does not flow to the Combined Sewer System (Yes/No)	Estimated Volume (gallons)	Explanation for how volume estimated or why it was not estimated	Supporting Documentation for volume estimation (e.g. photos) - Yes/No	Notified SF Regional Water Quality Control Board for Excursions over 1,000 gallons (Yes/No)	Notified SF County Department of Public Health for Excursions over 1,000 gallons (Yes/No)	Date and Time SF Regional Water Quality Control Board Notified for Excursions over 1,000 gallons	Date and Time SF County Department of Public Health Notified for Excursions over 1,000 gallons	Reported to CIWQS (Yes/No)	Date and Time Reported to CIWQS	Source (e.g. manhole, catch basin, vent trap)	Cause, including location (e.g. mainline blockage, roots, broken pipe, lack of hydraulic capacity, excessive surcharge)	
No	1-50	See Information Worksheet Row 17	See Information Worksheet Row 18	N/A	N/A	N/A	N/A	No	N/A	MH	ROOTS_ONLY	SEWER
No	1-50	See Information Worksheet Row 17	See Information Worksheet Row 18	N/A	N/A	N/A	N/A	No	N/A	MH	OTHER	MANHOLE

Associated with a storm event (Yes/No)	Response activities to mitigate and cleanup	Disinfection (Yes/No)	Corrective Actions taken	Samples taken (Yes/No)	Parameters for which samples were analyzed	Sample Results	County Health Officer notified (Yes/No)	Date and Time County Health Officer notified	Health warnings posted (Yes/No)	Location of health warnings (e.g. latitude, longitude)	Date and Time Health warnings posted	Date and Time Health warnings removed
0	flushed m/s with harben	Yes	See Information Worksheet Row 30	No	N/A	N/A	See Information Worksheet Row 34	See Information Worksheet Row 35	N/A	N/A	N/A	N/A
	flushed m/s with harben		See Information Worksheet Row 30	No	N/A	N/A	See Information Worksheet Row 34	See Information Worksheet Row 35	N/A	N/A	N/A	N/A

[illegible]

ptions from Excursion Database	Narative comments or descriptions from the work orders associated with excursion
Relieved 8" MS on easement with Harben by myself,pulled out several rootballs,flushed multiple times over problem area,used sevral tanks of water.I made SRO for MS TV with Vac last time here a few months ago.I flushed this from MS off Selma stairs.	See Information Worksheet Row 50
from manhole @ 200 wheeler, also main sewer in easement does NOT show on asset map addresses include 235-265 hester	See Information Worksheet Row 50